

# Plate 2

## Explanation

### Landslide symbols

Type of landslide shown by pattern and activity shown by color

	Historic	Young	Mature
Debris Flow			
Debris Slide			
Rock Slide			

Confidence of Interpretation shown by outline

Definite	Probable	Questionable



# LANDSLIDES IN THE INTERSTATE 5 CORRIDOR BETWEEN VALENCIA AND GORMAN, LOS ANGELES COUNTY, CALIFORNIA

by

B.D. Foster

CALIFORNIA GEOLOGICAL SURVEY

### Geologic Structure Symbols

Geologic structure symbols included on this landslide map to show relation between dip of beds and fold axes and landslides.

- strike slip fault
- ..... strike slip fault, concealed
- ↑↓— anticline axis, approximately located
- .....↑↓..... anticline axis, concealed
- ↓↑— syncline axis, approximately located
- .....↓↑..... syncline axis, concealed
- .....↓↑?..... syncline axis, queried
- ┆ inclined bedding
- ⊥ overturned bedding